


# E-Motion 2-leg elektric adjusting - DL5/DL6 IC



- Crossbar containing 3 parts
- 1 pcs 2-meter cable
- 1 pcs adjusting panel (2 pcs 3,5x20 screws)
- 1 pcs adapter w/180 cm cable for 220 V 3 pcs cable clips

How to reset adjust-function:

- 1 - Press the "down-button" and lower the table as much as possible, hold the button until the table stops moving
- 2 - Repeat pressing the "down-button" and hold until the table stops moving.

**The table is now reset for adjusting.**

Pictures, FDV, dwg:



eller:

<https://scansorlie.no/produkt/e-motion/>

SCAN SØRLIE